SERVICE INFORMATION

Tech. Customer Service VKT 20 Gi/Zr/Go	Motorcycles R50/5, R60/5, R75/5 group: el. equipment	Munich, Dec. 70 No. 3/70 (298) eng.

Ref.: Rotor of the threephase generator

Dear Sirs,

At the motorcycle models

R 50/5 as from chassis No. 2 901 772
R 60/5 " " " " 2 932 606
R 75/5 " " " " 2 973 649

we install better generator rotors, the coils of which are fixed against torsion vibrations by a double dipping method. The bettered rotors are marked with a white or blue point at the face side of the clamp poles, e.g. of the grinding rings.

If the red charge control lamp is not burning or only very weak and if the starter shows no reaction when pressing the button - of cycles of the indicated frame Nos. at switched on ignition and standing engine - the cause is an interruption of the field coils of the generator runner. For repair use runner ordering No. 12 31 8 002 347.

This runner is available in the usual spare parts way.

The part costs and the necessary work time of 7 FR are to be invoiced by warranty claims.

Yours very truly,
BAYERISCHE MOTOREN WERKE
Aktiengesellschaft
ppa. i.V.

Delleske Bennewitz

Kenntnis genommen - Pris connaissance - Noted - Tomado nota - Preso conoscenza					Ablage - Archives - File - Archivo	
Betriebsleitung Direction Management	Werkstatt Atelier Workshop	KD-Annahme Réception clientèle Cust. reception	Gewährl.-Sachb. Inspecteur garantie Warranty inspector	E-Teildienst Service pièces délachées Spare parts service	Betriebsleitung Direction Management	Werkstatt Atelier Workshop