



# SERVICE INFORMATION

Technical Customer Service  
VKT 20 gi/Zr/Go

Motorcycle R 75/5  
Group: engine

Munich, Nov. 70  
No. 3/70 (281)end

Supplement 1

Ref.: Carburettors

Dear Sirs,

Messrs. Bing have altered the designation of the equip-  
pression carburettors. Against the indication in S.I.  
No. 3/70 (281), in the Owner's Manual and in the Work  
shop Manual it must read:

carburettor Bing left side 64/32/3  
carburettor Bing right side 64/32/4

The ordering Nos. remain unaltered.

Yours very truly,

BAYERISCHE MOTOREN WERKE  
Aktiengesellschaft  
ppa. i.v.

Delleske

Bennewitz

Kenntnis genommen - Pris connaissance - Noted - Tomado nota - Preso conoscenza					Ablage - Archives - File - Archi		
Betriebsleitung Direction	Werkstatt Atelier	KD-Annahme Réception clientèle	Gewährl.-Sachb. Inspecteur garantie	E-Teildienst Service pièces détachées	Betriebsleitung Direction	Werkstatt Atelier	