

Service-Information



Group 11 Engine	February 1980	Bulletin No. 11 014 80(2015)
--------------------	------------------	---------------------------------

- For U.S.A. and Canada Only -

Subject: Sealing Cap for Chain Tensioner Bore -
from model year 1979 with hydraulic chain
tensioner.

To prevent any risk of the sealing cap falling out of the bore in which the hydraulic chain tensioner piston and coil spring are located, the cap will in future be secured by punch marks at two points (see drawing overleaf).

If you have to perform any repair work on these motorcycles, please check whether the punch marks have been provided. If not, secure the disc as shown, using a suitable punch.

BMW MOTORRAD GMBH
After-Sales Service
Munich