

# Service-Information



Tech.Cust.Service VS-2011 K1/La/Go	Motorcycles R75/6 - R90S Group: 34	Munich, July '74 1/74 (130 M) e
---------------------------------------	---------------------------------------	------------------------------------

## Supplement I

Re: Disc brakes on our /6 models

Gentlemen:

In the event of the brake fluid warning light lighting up despite the brake fluid container having been filled correctly to the maximum mark a topping up to the lower edge of the filler pipe is recommended.

In order to avoid a reduction in the brake friction value, the grooves in the brake pads are to be checked for deposits and cleaned if necessary at every maintenance service.

This point will be incorporated in the next edition of our service booklet.

Sincerely yours,  
BAYERISCHE MOTOREN WERKE  
Aktiengesellschaft  
i.V. i.V.

Kortas

Scholz