

Service-Information



Group 12 Motor-Electrics	September 1979	Bulletin No. 12 002 79(2001)
-----------------------------	-------------------	----------------------------------

- For U.S.A. and Canada Only -

SUPPLEMENT I

Subject: Improved Distributor Contact Breaker
for R 65, R 80/7 to R 100 RT

By mistake, a white plastic cap was included in the new set of contact breakers, part no. 12 11 1 243 969.

Please be sure not to install this white plastic cap which, if installed, will interfere with the operation of the contact breaker arm.

If you have, in the past, installed the above set of contact breakers, please inspect them upon the next customer visit to your shop for service and remove the white plastic cap.

Yours truly,

BMW MOTORRAD GMBH
After-Sales Service