

# Service-Information



Group: 33 Rear Wheel Drive	June 1981	Bulletin No: 33 006 81 (2033)
-------------------------------	--------------	----------------------------------

- For U.S.A. and Canada Only -

RE: Nivomat

Since the introduction of the "Nivomat" rear shock, now standard on all 1981 RT Models, it has come to our attention that premature failures occur due to:

1. FILLER PLUGS:

WARNING:

Do not remove or loosen these two phillip head screws. If done, the entire shock will be ruined and must be replaced at your cost.

These holes are for manufacturing purposes only, no adjustments or rebuilding can be achieved by removing these screws.

2. WARRANTY:

If it is necessary to exchange the units, then an advanced authorization of your District Service & Parts Manager must be received and all defected units sent back to Norwood, New Jersey, Attn: Warranty Dept., for inspection.

3. WARRANTY COVERAGE:


- A. One year, unlimited mileage on 1981 RT Models only.
- B. Six months, unlimited mileage on all Nivomats purchased from us for installations on all previous models.

All special "Nivomats" for the R65 will be available soon.

Yours truly,

Herb Neas  
National Service Manager

/bb



TAKE ON OFF & PUMP  
REAR OF BIKE SEE IF  
IT COMES UP