



SERVICE INFORMATION

Customer Service
V.GmbH/B&S, N.J.

Motorcycles R50/5, R60/5, R75/5
Brakes, Wheels and Tires

New Jersey, Nov. 1969
Nr. 1/69 (274)

Subject: Inspection and Adjustment of Steering Head Bearing, and Wheel Bearing on New Motorcycles

Gentlemen:

The recommended inspection and adjustment of the steering head bearings and wheel bearings (as listed under No. 10 of the second free service inspection at 1000 miles) should be performed during

the first free service at 300 miles

this inspection now has the additional item number 5

- 5. Check fork and wheel bearings adjust if needed.

This procedure does not have to be repeated at the 1000 mile service.

The wheel bearing adjustment should be performed according to the instructions on page 36-31/3 of the Repair manual, the steering head bearing adjustment should be performed according to instructions on page 32-00/1 of the Repair manual.

Bayerische Motoren Werke
Aktiengesellschaft


- Volker Beer -

Kenntnis genommen — Pris connaissance — Noted — Tomado nota — Preso conoscenza					Ablage — Archives — File — Archivo		
Betriebsleitung Direction	Werkstatt Atelier	KD-Annahme Réception clientèle	Gewährl.-Sachb. Inspecteur garantie	E-Teildienst Service pièces détachées	Betriebsleitung Direction	Werkstatt Atelier	