



Service-Information



BMW Motorrad GmbH
Service Ett/mk/fm

Motorcycles R60/6 - R90 S
Technical
Group 23

Munich, Dec '75
1/75 (204 M) e

Subject: Connection between universal shaft and gearbox
- torque values changed

The torque of the four 12-sided bolts on the drive shaft coupling has been increased from 25^{+3} Nm (2.5 + 3.0 mkp) to:

38^{+4} Nm (3.8 + 0.4 mkp)

The quality of the bolts is of such high standard that it allows the increased torque specifications.

In this connection, we also refer again to the BMW service bulletin 4/74 (139 M). It is an essential procedure to check the torque of the 4 bolts during the pre-delivery inspection before delivery of the motorcycle to the customers.

Sincerely yours,
BMW MOTORRAD GMBH
München
i.V. i.A.


Ettlich Lesemann

Kenntnis genommen - Pris connaissance - Noted - Tomado nota - Preso conoscenza				Ablage - Archives - File - Archivio		
Betriebsleitung Direction	Werkstatt Atelier	KD-Annahme Reception clients	Gewähr-Sachb. Inspecteur garantie	Teiledienst Service pièces detachees	Betriebsleitung Direction	Werkstatt Atelier