SERVICE INFORMATION

Tech. Cust. Service VKT 20 Gi/Zr	Motorcycke R 50/5,R60/5,R75/5 Group: Frame	Munich, April 71 No. 1/71 (309)en

Ref.: Torque for clamp screws of t e rear knockout spindle

Dear Sirs,

Due to a given reason, we want to point out that the torque for the clamp screws of the rear knockout spindle is 1.6 ± 0.2 mkp and this has to be exactly observed. If you surpass this value, there is the danger of a follow damage.

Yours very truly,

BAYERISCHE MOTOREN WERKE
Aktiengesellschaft

ppa. i.V.

Delleske Flohr

Kenntnis genommen - Pris connaissance - Noted - Tomado nota - Preso conoscenza					Ablage - Archives - File - Archivo	
Betriebsleitung Direction	Werkstatt Atelier	KD-Annahme Réception clientèle	Gewährl.-Sachb. Inspecteur garantie	E-Teildienst Service pièces détachées	Betriebsleitung Direction	Werkstatt Atelier