

Service-Information Motorcycle



BMW NA
Service Department

Group: 61
Electrics

February 1989
61 020 89
(2343)

For USA Only

Brake Light Switch Recall

Information: This Service Information is being sent to all dealers in advance of customer or press notification.

We are targeting **April** for official customer notification by mailing a letter describing the defect to each customer whose motorcycle is in the affected range. A detailed Service Information is being drafted now to explain the necessary parts and modifications needed for each dealer to perform this Recall.

Prior to the Recall announcement, you will be sent a list of affected new motorcycles in your inventory. It is your responsibility to perform this Recall to all affected motorcycles in inventory prior to the retail sale.

To aid you in performing this Recall a chart, which you can use in researching your records for customer information, will also be sent. This will enable you to schedule appointments for the repair, plus any additional work that may be appropriate.

**Important
Notice:**

This Recall affects more than the Brake Light Switch. There are other modifications which also must be performed. **Every motorcycle will not need a new Brake Light Switch, so take no action until notified by a Service Information bulletin.**

Very truly yours,

BMW of North America, Inc.

A handwritten signature in black ink, appearing to read 'Frank Stevens'.

Frank Stevens
National Service Manager

A handwritten signature in black ink, appearing to read 'Richard Dampf'.

Richard Dampf
National Technical Manager

FS:je1/196.5