



SERVICE INFORMATION

Technical Customer
Service - VK¹-20 Gi/St

Motorcycle 1- + 2-cylinder
models - Gr.: Frame

München, Sept. 1970
n. 1/70 (291) en.

18

Subj.: Calcite on exhaust pipes

Dear Sirs,

To remove calcite - it deposits especially on the bottom part of the exhaust pipes, resulting from water sprays - we tested various products in our laboratory.

The product VP 2693 proved especially effective. It is a rust remover paste, produced by the company

Metallgesellschaft AG
Frankfurt
Reuterweg 14

which, in spite of a reaction period of several days, did not attack the basic metal of the corresponding parts.

The duration for the use of the paste depends on the thickness of the calcite and so varies from case to case.

After having removed the calcite, the paste has to be washed off carefully so that the corrosive phosphoric acid, contained in this product, will not attack the chrome plating.

Very truly yours,

BAYERISCHE MOTOREN WERKE
Aktiengesellschaft

ppa.

i.V.

Delleske

Bennewitz

Kenntnis genommen - Pris connaissance - Noted - Tomado nota - Preso conoscenza					Ablage - Archives - File - Archivio		
Betriebsleitung Direction Management	Werkstatt Atelier Workshop	KD-Annahme Réception clientèle Cust. reception	Gewährl.-Sachb. Inspecteur garantie Warranty inspector	E-Teildienst Service pièces détachées Spare parts service	Betriebsleitung Direction Management	Werkstatt Atelier Workshop	