

- 2 -

Shortly after the installation of the new automatic timing mechanism the dwell angle of the contact-breaker was also reduced from 110° to 78° ; this prevents overheating of the ignition coils of fully suppressed engines when driven extremely hard.

Yours very truly,
BAYERISCHE MOTOREN WERKE
Aktiengesellschaft
Kundendienst

ppa.


Delleske


Blohr