



SERVICE INFORMATION

Tech. Cust. Service VS-201 fm/zr	Motorcycles R50/5, R60/5, R75/5 group: gearbox	Munich, Nov. 11 No. 3/71 (317) e.
-------------------------------------	---	--------------------------------------

Ref.: Thrust washer at drive shaft

Dear Sirs,

caused by further technical development we started in the series ex

chassis No.	2 903 693	-	R 50/5
"	2 938 962	-	R 60/5
"	2 982 820	-	R 75/5

a improved thrust washer and altered the bushing for the drive shaft of the gearbox.

present version	part No.	
starter disc and bushing	2 321 1 020 164	1,5 mm thick
	2 321 1 230 446	2,5 mm thick

improved version	part No.	
starter disc and bushing	2 331 1 231 392	2,0 mm thick
	2 321 1 231 393	2,0 mm thick

We keep the present versions on stock for Earl's type fork models R 50, R 60 and R 69.S.

- 2 -

Kenntnis genommen - Pris connaissance - Noted - Tomado nota - Preso conoscenza				Abilage - Archives - File - Archivio		
Betriebsleitung Direction Management	Werkstatt Atelier Workshop	KD-Annahme Réception clientèle Cust. reception	Gewährl.-Sachb. Inspecteur garantie Warranty Inspector	E-Teildienst Service pièces détachées Spare parts service	Betriebsleitung Direction Management	Werkstatt Atelier Workshop