

Service-Information



Group: 61 General Electrics	March 1982	Bulletin No.: 61 009 82 (2049)
--------------------------------	---------------	-----------------------------------

- For U.S.A. and Canada only -

RE: CORROSION PROTECTION OF ALL ELECTRICAL CONTACTS

Dear Dealer:

In some instances, due to weather or other environmental influences, sometime also caused by excessive water spray when cleaning the motorcycle, corrosion may be formed at electrical connectors or contacts.

To prevent this, at the time of assembly, we preserve all of this area by using a spray material. However, this protection only lasts for some time; we therefore recommend that on a yearly basis you spray these contacts, such as on the distributor, generator, ignition coils, starter motor, spark plugs, relays, etc.

We recommend brand names such as

WD 40 or CRC 556

Yours truly,

A handwritten signature in black ink, appearing to read 'H. Neas'.

H. Neas
National Service Manager

HN/vaa