

Service-Information



Tech.Cust.Service VS-201 kl/LP/st	Motorcycles R 50/5 - 75/5 Group 23: Gearbox	Munich, June '73 No. 1/73 (072M)e
--------------------------------------	------------------------------------------------	--------------------------------------

Ref: Gearbox oil level

Dear Sirs,


We would advise you to maintain the prescribed oil level in the gearboxes of our motorcycles, as too little oil could result in the premature wear of the bearing bushings.

Please ensure at each service that the oil level is at the lower thread of the filler hole - if necessary, top up with branded hypoid gear oil SAE 80 or 90 according to ambient temperature.

Yours faithfully,

BAYERISCHE MOTOREN WERKE
Aktiengesellschaft
ppa. i.v.


Delleske


Flohr