

# SERVICE INFORMATION

Tech.Cust.Service  
VKT 20 gi/zr/hn

Motorcycle R 75/5  
group: engine

Munich, Dec. 1970  
No. 5/70 (284)

## Supplement 2

Re.: Advanced constant pressure carburetor

Dear Sirs,

The refitting of the constant pressure carburetors of model R 75/5 until chassis No. 2 972 061, started by S.I. 5/70 (284), has not yet been effected to all engines, though enough refitting kits are available.


We point out once again that all engines concerned have to be transformed as soon as possible and we order our field engineers to control this action.

All engines have to be transformed immediately.

Yours very truly,

BAYERISCHE MOTOREN WERKE  
Aktiengesellschaft  
ppa. i.V.

  
Delleske

  
Bennewitz

Kenntnis genommen - Pris connaissance - Noted - Tomado nota - Preso conoscenza					Abiage - Archives - File - Archivo		
Betriebsleitung Direction Management	Werkstatt Atelier Workshop	KD-Annahme Réception clientèle Cust. reception	Gewährl.-Sachb. Inspecteur garantie Warranty inspector	E-Teildienst Service pièces détachées Spore parts service	Betriebsleitung Direction Management	Werkstatt Atelier Workshop	

