

Service-Information



Group: 36 Wheels & Tires	March 1982	Bulletin No.: 36 014 82 (2058)
-----------------------------	---------------	-----------------------------------

- For U.S.A and Canada only -

RE: METZLER TIRES - "ENDURO" 400-18 64R FOR R80G/S
MODELS


Dear Dealer:

It is possible that the rear tire manufactured by Metzler and delivered to you as standard equipment, prematurely will develop cracks in the profile section of the tire. Metzler, in conjunction with BMW, has modified and tested the new, improved versions. The enclosed picture will identify the new design by the change of the profile in the middle of the tire. Front tires, 300-21 48R, have not been changed.

All defective rear tires and tubes can be claimed for directly to the Metzler distributor, or:

Metzeler Tire
P. O. Box 15536
Pittsburgh, Pennsylvania 15244
(412) 787-8880

Yours truly,


H. Neas
National Service Manager

HN/vaa
enclosure

