



# Service-Information



BMW MOTORRAD GMBH Service R-VK-10 wb-st	Motorcycle R 60/6 - R 100 RS Technical Group: Rear Drive	Munich, Nov.'78 33 003 78 (1064R)
---	--	--------------------------------------

- For U.S.A. and Canada Only -

Subject: Rear Drive Gear Ratios

Dear Dealer,

Below is a gearing information chart for your convenience.

Whether checking, repairing, or ordering replacement gears or speedometers make sure ratios are accurate. Continuing changes make parts microfiche listings inaccurate.

We must also remind you not to change any gearing on machines built after January 1, 1978 due to EPA emission regulations.

Ratio	No. of Teeth Ring Gear/Pinion Gear	RPM at 55 mph (101 km/h) (approx*)	Speedometer Ratio (mph)
2.91 to 1	32/11	3050 + 4%	1.078
3.00 to 1	33/11	3147 + 4%	1.112
3.09 to 1	34/11	3241 + 4%	1.144
3.20 to 1	32/10	3357 + 4%	1.186
3.36 to 1	37/11	3525 + 4%	1.244
3.44 to 1	31/9	3608 + 4%	1.259
3.56 to 1	32/9	3734 + 4%	1.318

\* Based on original equipment tires and depending upon inflation pressure, wear, and manufacturing tolerance of the tire.

Yours truly,

BMW MOTORRAD GMBH  
Munich

i.V.

*Herrn*  
Gonzalez

i.V.

*Blank*  
Blank

Kenntnis genommen - Pris connaissance - Noted - Tomado nota - Preso conoscenza

Ablage - Archives - File - Archivio

Betriebsleitung	Werkstatt	KD-Annahme	Gewährl.-Sachb.	Teiledienst	Betriebsleitung	Werkstatt
-----------------	-----------	------------	-----------------	-------------	-----------------	-----------