



Service-Information



BMW MOTORRAD GMBH Service R-VK-10 MA-ST	Motorcycle R60/7-R100RS Technic Brakes	Munich, Sept.77 34 002 77(1030R)
---	--	-------------------------------------

For U.S.A. and Canada only

Subject: Splash Guard for Rear Brake Master Cylinder.

Dear Dealer,

A recent change and addition on the assembly of new models is a splash guard on those models equipped with a rear disc brake.

For those that wish such an improvement, the guard:

BMW Part No. 34 31 1 238 040

is available through the parts channel.

Installation is easy, just disconnect the brake rod and slide over the rubber splash guard.

Yours truly,

BMW MOTORRAD GMBH
Munich
i.V. i.V.

Mario Gonzalez
Gonzalez

Blank
Blank

Kennnis genommen - Pris connaissance - Noted - Tomado nota - Preso conoscenza					Ablage - Archives - File - Archivio	
Betriebsleitung Direction	Werkstatt Atelier	KD-Annahme Reception clientele	Gewahl - Sachb inspecteur garantie	Teiledienst Service pieces detachees	Betriebsleitung Direction	Werkstatt Atelier