



SERVICE INFORMATION

Tech. Cust. Service
VS-201 gi/zr

Motorcycles R50/5, R60/5, R75/5
group: brakes, wheels, tires

Munich, Sept. 1971
No. 2/71 (313) e.

Ref.: Rim tape

Dear Sirs,

Instead of the actually mounted rim tape ex


R 50/5 chassis No. 2 903 611
R 60/5 chassis No. 2 938 469
R 75/5 chassis No. 2 982 575

an adhesive textile tape, 30 mm broad, with impregnated rear surface is fixed. This has been tested with success for years already in motor sports and shows the following advantages:

1. When mounting a tire a slipping of the rim tape and a damage at the tube by spoke ends is no more possible.
2. At a faulty tube air cannot go out by one step via the spoke holes, because the rim tape covers the holes quite good. By this the accident risque at defect tires is lowered essentially.

We use in the series the tape Tesa 657; tapes can be ordered via special supply firms.

Yours very truly,
BAYERISCHE MOTOREN WERKE
Aktiengesellschaft
Service Division
ppa. i.V.


Delleske

Flohr

Kenntnis genommen - Pris connaissance - Noted - Tomado nota - Preso conoscenza					Ablage - Archives - File - Archivio		
Betriebsleitung	Werkstatt	KD-Annahme	Gewährl.-Sachb.	E-Teildienst	Betriebsleitung	Werkstatt	