

Service-Information



Tech.Cust.Service VS 201 LP/sta/fm	Motorcycles R50/5, R60/5 R75/5 Group: Engine	Munich, Nov 72 5/72(043 M) e
---------------------------------------	----------------------------------------------------	---------------------------------

Ref: Rocker arm bearing supports

Dear Sirs,

To suppress noise which can occur if there is too much play on the rocker arm, slotted rocker arm bearing supports (Order No. 11 12 1 250 237) used in conjunction with a hardened thrust washer (Order No. 11 33 1 257 825) have been introduced in series production upwards of

Chassis No.	2 904 721	for the model	R 50/5
"	" 2 942 632	" " "	R 60/5
"	" 2 989 472	" " "	R 75/5

These new supports guarantee a perfect fit on the rocker shaft so that the axial clearance always remains the same.

The new supports should be fitted with the flat surfaces lying on the rocker arm support sleeves. When fitted the slotted sides of the supports should be located opposite each other.

The rippled washer previously used is replaced by the new thrust ring. This should be inserted so that no rocker arm end play is evident although the rocker arm still moves easily around the shaft.

Yours faithfully,
BAYERISCHE MOTOREN WERKE
Aktiengesellschaft
Kundendienst

ppa.


Derleske


Fiohr