



# SERVICE INFORMATION

Tech.Cust.Service  
VS-201 Fm/Zr

Motorcycles R50/5,R60/5,R75/5  
group: engine

Munich, Nov. 71  
No. 4/71 (315) e.

Ref.: Spiral gear (speedometer drive)

Dear Sirs,

Starting with chassis Nos.

2 903 617 - R 50/5  
2 938 592 - R 60/5  
2 982 663 - R 75/5

we install between the upper starting surface of the spiral gear, parts no. 11 31 1 250 187, and the radial sealing ring, parts no. 11 31 1 256 563, a washer, parts no. 11 31 1 256 928.

By this a damage of the sealing lip of the radial sealing ring is avoided when the spiral gear moves up while coasting with the motorcycle.

Please install this washer when you notice oilleaks in this range.

Yours very truly,

BAYERISCHE MOTOREN WERKE  
Aktiengesellschaft  
Service Division

ppa.

i.v.

  
Delleske

  
Flohr

Kenntnis genommen - Pris connaissance - Noted - Tomado nota - Preso conoscenza

Ablage - Archives - File - Archiv

|  |                                  |  |  |  |  |                                  |
|--|----------------------------------|--|--|--|--|----------------------------------|
| Betriebsleitung<br>Direction<br>Management | Werkstatt<br>Atelier<br>Workshop | KD-Annahme<br>Réception clientèle<br>Cost. reception | Gewährl.-Sachb.<br>Inspecteur garantie<br>Warranty inspector | E-Teildienst<br>Service pièces détachées<br>Parts and services | Betriebsleitung<br>Direction<br>Management | Werkstatt<br>Atelier<br>Workshop |
|--|----------------------------------|--|--|--|--|----------------------------------|