

Service-Information



Tech.Cust.Service VS-201 gi/Zr/fm	BMW Motorcycles Group: Springs and Shock Absorbers	Munich, Feb 73 3/72 (045M) e
--------------------------------------	--	---------------------------------

Ref: Play adjustment of the bearings in the steering head

Dear Sirs,

The play of the tapered roller bearings in the steering head is adjusted as of

Chassis No. 2 905 828	R 50/5
Chassis No. 2 946 097	R 60/5
Chassis No. 2 995 073	R 75/5

by means of a nut, Part No. 31 42 1 232 343 instead of the split circular nut used previously.

As a result of this alteration, the following parts are no longer necessary:

<u>Parts designation:</u>	<u>Part Number:</u>
Split circular nut	31 42 2 005 315
Collet	31 42 2 000 311
Cheese-head screw 8x25	07 11 9 919 646
Hex. nut M 8	07 11 9 922 081

The new nut can be installed in the telescopic fork of the /5 models and also in the models R 50/US, R 60/US, and R 69/US.

Yours faithfully,
BAYERISCHE MOTOREN WERKE
Aktiengesellschaft
ppa. i.V.

Delleske

Scholz

Kenntnis genommen - Pris connaissance - Noted - Tomado nota - Preso conoscenza					Ablage - Archives - File - Archivio	
Betriebsleitung	Werkstatt	KD-Ausgabe	Gewähr-Sachh	Teledienst	Betriebsleitung	Werkstatt