



Service-Information



BMW MOTORRAD GMBH Service RM-K-11 fa	Motorcycle-R 65-R 100 RT Technical Group: Electric	Munich, July '79 61 00 3/79(1074R)
--	--	---

- For the U.S.A. and Canada Only -

Subject: Possible Defects of the Electric
Handlebar-Mounted Switches

Dear Dealer,

In case of problems, hanging up or non-operation of handlebar-switches, such as: directionals, starter, horn, lights, engine cut-off button, the entire unit must be exchanged.

Repairs falling under the standard warranty, the entire unit should be claimed using the following labor reimbursement rates:

R 65	:	4 FRU
R 80/7 - R 100 T	:	6 FRU
R 100 S	:	10 FRU
R 100 RS	:	8 FRU
R 100 RT	:	8 FRU

Yours truly,

BMW MOTORRAD GMBH
Munich

H. Gonzalez
 i.V.
 Gonzalez

J. Blank
 i.V.
 Blank