## Service-Information Motorcycle



Group:

BMW NA

3

May 1991

Service Department

Equipment Advice XIV/91 (2454) For USA Only

Main Bearing Installation Special Tools - All Boxer Models

The following tools are available through normal parts channels.

The uses of these Drill Bits and Reamer are described in the Repair Manual microfiche for all Boxer models:

88 88 6 999 040 - 4 mm Reamer

88 88 6 000 039 - 3.9 mm Drill Bit

88 88 6 000 038 - 3.8 mm Drill Bit

88 88 6 000 032 - 3.2 mm Drill Bit

Very truly yours,

BMW of North America, Inc.

Frank Stevens

National Service Manager

Motorcycle Group

FS:jel/11.1

Richard Dampf

National Technical Manager

Please initial and route to the following before filing				
Service	Parts	Sales	Warranty	Technicians