

Service-Information



Group: 11 Engine	March 1982	Bulletin No.: 11 023 82 (2052)
---------------------	---------------	-----------------------------------

- For U.S.A. and Canada only -

RE: CYLINDER BASE O-RING

Dear Dealer:

For replacement, an additional "O"-ring has been introduced with an 0.2 mm thicker diameter.


This new O-ring will fit all older models with "O" rings of a diameter of 2 mm. and will enhance better sealing.

This new 2.2. mm O-ring is available through regular parts channels under

Part No. 11 11 1 337 567

Yours truly,

BMW OF NORTH AMERICA, INC.


H. Neas
National Service Manager

HN/vaa