SERVICE INFORMATION

Tech. Customer Service VKT 20 Gi/Zr/Go	Motorcycles R 50/5,R60/5, R75/5 group: electrical equipment	Munich, March 71 No. 3/71 (298) eng.

Supplement 1

Ref.: Rotor of the 3-phase-generator

Dear Sirs,

Messrs. Bosch informed us that the new rotors of the 3-phase-generator are no more marked with a blue point since Dec. 70. We want to point out that the rotors with the fabrication code No. 032 e.g. 121 ff are the latest model.

Yours very truly,
BAYERISCHE MOTOREN WERKE
Aktiengesellschaft
ppa. i.V.

Delleske Scholz

Kenntnis genommen - Pris connaissance - Noted - Tomado nota - Preso conoscenza					Ablage - Archives - File - Archivo	
Betriebsleitung Direction Management Dirección	Werkstatt Atelier Workshop Taller	KD-Annahme Réception clientèle Cust. reception Recepción clientela	Gewährl.-Sachb. Inspecteur garantie Warranty inspector Inspector garantía	E-Teildienst Service pièces détachées Spare parts service	Betriebsleitung Direction Management	Werkstatt Atelier Workshop